

City Of Kalamazoo

Wastewater Division

Instrument Tech Building

Section 3

<u>Deficiency</u>	<u>Qty</u>
Caulk Failure	37
Failing Penetration	1
Failing Penetration	8
Improper Installation	1

Section 4

<u>Deficiency</u>	<u>Qty</u>
Open Flashing	1

Raw Pump Building

Section 1

<u>Deficiency</u>	<u>Qty</u>
Loose Debris	3
Open Flashing	13
Failing Penetration	22
Open Flashing	105
Skylight Leaking (Replace tops)	8
Caulk Failure	86
Lost Adhesion Sq ft	200
Punctures - Rips - Tears	1
Water Test	1

Section 2

<u>Deficiency</u>	<u>Qty</u>
Caulk Failure	20
Open Flashing	16

Section 3

<u>Deficiency</u>	<u>Qty</u>
Caulk Failure	15
Open Flashing	8

Section 4

<u>Deficiency</u>	<u>Qty</u>
Open Flashing	3
Open Flashing	20
Caulk Failure	18

Primary Skimmer

Section 2

<u>Deficiency</u>	<u>Qty</u>
Open Flashing	1
Damaged Insulation	9sqft

Section 3

<u>Deficiency</u>	<u>Qty</u>
Clogged Drain	1
Damaged Insulation	21sqft

Section 4

<u>Deficiency</u>	<u>Qty</u>
Damaged Insulation	18sqft